




- MERTT
  - ★ Helicopter
  - Replacement Tree
  - Special Attention ITAN
  - Unit Complaint
  - + TGR Tree
  - ▲ RM 43 Mature Tree
  - - - Access Route
  - Road Centerline
  - Sensitive Parcels
  - Parcels
  - Planner Notes
  - Substation
  - Transmission ROW
- 
- Off Cycle Tree Risk
  - Engineer
  - Heavy Prune
  - Line Crew
  - Removal
  - Resolved
- 
- ◆ Complete Refusal
  - ◆ Scope Modification
  - ◆ Standard Removal
- 
- Special Needs Tree
  - Complete Refusal
  - Scope Modification
  - SNL
  - SNW
  - None
- 
- Vine Pole
  - RM
  - PM
  - Capital
  - Comprehensive Work
- 
- Linear Trim
  - Complete Refusal
  - Scope Modification
  - After FPD - Dist.
  - Before FPD - Dist.
  - Transmission Linear Trim
- 
- Wall Trim
  - Complete Refusal
  - Scope Modification
  - After FPD - Dist.
  - Before FPD - Dist.
  - Transmission Wall Trim
- 
- Main. Priority ITAN
  - Immediate Attention
  - Work Not Required
  - Work Required
- 
- Brush
  - Complete Refusal
  - Scope Modification
  - Herbicide
  - Cut Brush/ Hand Cut
  - Mowing
- 
- Transmission Structures
  - Pole
  - ▲ Transmission Tower
- 
- Poles (Owner)**
  - ACE
  - BGE
  - Bell
  - CATV
  - Choptank
  - City of Wilmington
  - Customer
  - DPL
  - Electric
  - Foreign Electric
  - Pepco
  - Private
  - Railroad
  - State Highway
  - Unknown
  - Verizon
- 
- Fuse (Status)**
  - Closed
  - Not Applicable
  - Open
  - Unknown
- 
- Switch (Status)**
  - Closed
  - Not Applicable
  - Open
  - Unknown
- 
- Recloser Bank (Status)**
  - Closed/Unknown/NA
  - Open
- 
- Overhead Transmission/ Distribution Lines**
  - Phase 7
  - Phase 6
  - Phase 5
  - Phase 4
  - Phase 3
  - Phase 2
  - Phase 1
  - Voltage 23
  - Voltage 34.5
  - Voltage 69
  - Voltage 138
  - Voltage 230
  - Voltage 500



Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), TomTom, MapmyIndia, © OpenStreetMap contributors, and the GIS User Community

